


Repeatability vs. Reproducibility: Who would use repeatability and/or reproducibility?

Both repeatability and reproducibility are essential in nearly all areas of science, including chemistry, computer science, data science, and engineering. A line operator in a manufacturing facility may rely more on repeatability, whereas a chemist developing a new chemical reaction would strive to achieve reproducibility of their experimental method and rely on repeatability data to determine its accuracy.









SANS 10270:2015

Edition 1.3

Choosing Between Repeatability and Reproducibility: Real World Scenarios

To Do or Not to Do

Let's say a quality inspector is measuring the weight of different sized bolts to ensure they are within the acceptable range before sending them through to the next step in the manufacturing process. To determine the reliability of the scale, the head engineer wants the operator to weigh each bolt multiple times and record their results. Essentially, the operator is performing a repeatability test. The engineer notices that the scale appears to be having a significant variation in bolts that weigh more than 50 grams. The conclusion is that a different scale capable of producing repeatable measurements on the same bolts over 50 grams needs to be installed at the quality inspector's station. This simple repeatability test allowed the engineer to catch a potential area of inaccuracy in the manufacturing process and potentially avoid costly quality and functional issues in the end product.

Reproducibility is a major goal of research teams and collaborations in the field of chemistry. Let's say a team of chemists has produced a chemical reaction that can create a nickel complex that absorbs near-infrared light. The team has designated one of its members to perform the test multiple times and record their data. They have come to the conclusion that their experiment is repeatable. The team is in collaboration with another team working on the same goal of producing safer materials for solar panels. They send their method to the other team and ask them to perform the experiment multiple times and record their data. Several of the other teams' members reproduce the same results as the original team. The experiment can now be deemed reproducible, and the team can move on to improving the process so it can be scaled for production.

SOUTH AFRICAN NATIONAL STANDARD

Welding of thermoplastics — Approval of welding procedures and welds

Summary

Depending on what industry you work in, you may need to use repeatability and/or reproducibility tests. If you are simply trying to determine the accuracy or consistency of a measuring tool, repeatability tests are likely all you need. However, if you are developing new processes and/or products, both repeatability and reproducibility are essential in the process of moving your ideas from planning to experimentation to production.







15-06-2023




To Do or Not to Do- Normative Standards in ISO 4427


















Presenter

SAPPMA Webinar III 2023

15 June 2023



Saravanan Babu







Theories about Thermoplastic Welding

Welding is an interaction at the interface of surfaces of interatomic and

intermolecular forces.

- Adhesion theory: ratio of surface energies of the two materials where the maximum adhesion is obtained in the case of identical material where the specific contact surface energy is zero.
- Viscoelastic contact theory: molecular forces such as Van Der Waals act on the surfaces which deformed under welding pressure, forming a boundary surface as a function of time.
- Diffusion theory: diffusion of chains or chain segments across the weld interface, provided that the polymers are mutually soluble, and the molecules have sufficient mobility achievable by exceeding a certain minimum temperature threshold.
- Flow process theory: mechanical displacement of chains in the flow field generated by the welding pressure and temperature, forcing mixing to occur as a result of both thermal and mechanical displacement processes.





HDPE Pipe Welding Techniques

High-density polyethylene (HDPE) pipes are widely used in oil and water systems due to their ease of installation, long service life, good corrosion resistance, environmental protection ability, and excellent mechanical properties.

In order to ensure the water-tightness and integrity of the pipeline, HDPE pipes are usually welded with various techniques.

The main welding methods for HDPE pipes for pressure transmission applications are butt fusion welding and electrofusion welding.

Extrusion welding is a technique followed to weld structured wall HDPE pipes which are manufactured in accordance with ISO 21138 standards.





Significance of a Good Pipe joint

 Proper Engineering design of a pipeline involves the consideration of the type and effectiveness of the techniques used to join the pipeline components as well as the durability of the resulting joints.







Factors influencing the Weld Quality

Cleanliness: In the field of welding, no matter what the material, cleanliness matters and should be emphasized throughout the process.

- Machines shall be clean
- · Pipe surface, welding materials shall be clean
- Welding area should be protected at the construction site

All such parameters shall be designed to prevent contaminants getting into the weld which might reduce the lifetime of the asset being installed.





Factors influencing the Weld Quality

Heat energy: To make a satisfactory weld the pipe/weld material must be heated such that all the material at the end of the pipes to be joined has achieved the target temperature for the operation and holds this temperature until the pipe ends pressed together.

Too much heat may degrade the material, too little heat affects the weld strength, so the key is to achieve the target temperature range set out in the specifications.

Pressure: The pressure, sometimes referred to as the interfacial pressure experienced by the pipe ends when they are butted against each other matters.

Pressure is used to ensure the molten pipe ends are fully squeezed together to form an intimate connection so the minimum level matters.

Too much pressure can squeeze all the molten material out of the welded area. So, a target range matters.



Factors influencing the Weld Quality

Time: Each of the cycle times has a design intent behind it, whether this is ensuring adequate time for heat to soak into the pipe ends, ensuring they don't cool down too quickly when heater plates are removed and so forth.

But what also matters is allowing the joint to cool properly in the clamps when a weld has been made, the material has to reform its crystalline structure to allow it to be handled without damage.





The 5M's affecting the Weld Quality

5M structure Machinery Management Methods Material Manpower Procedures Organizational • Raw Qualifications License structure Materials Instructions · Habits Durability Organization • Items Responsibilities Modernity · Job of work satisfaction Specifications •Semi- Security Working finished Internship Standards Efficiency conditions products ·Well-being



The 5M's affecting the Weld Quality - Manpower

The key to the success of any welding process is based on the skills of the welder and the dedication to correct surface preparation and follow correct weld procedures.

All welding operators should be qualified and regularly recertified with a qualification test.

DVS 2212, SANS 10269



The 5M's affecting the Weld Quality - Manpower

WELDER IDENTIFICATION AND TRACEABILITY

S/N		NAMES	WELD IDENTIFICATION NO.
1	MIRAJI	ALLY	PF - 106
2	ALLY	SHABANI	PF - 172
3	MARCELIUS	NCHIMBI	PF - 174
4	ABDUL	MOHAMED	PF - 177
5	RUDIEL	LEMA	PF - 236







The 5M's affecting the Weld Quality – Method

The SANS 10268 (part 1 to 10)/DVS 2207 (part 1 to 10) is a series of standards applies to jointing thermoplastic materials.

The first part of the standard discusses heated tool welding of PE-HD sheets, pipes, and pipeline components.

In addition, this section covers heated plate butt welding, socket welding, and electro-fusion welding of pipes.

In these standards, instructions for how to prepare components for welding, how to carry out welding itself, and how to test the welding are laid out and identify defects along with allowable tolerances.

SANS 10268-1	2009	1.03	Welding of thermoplastics - Welding processes Part 1: Heated-tool welding
SANS 10268-2	2004	1.01	Welding of thermoplastics - Welding processes Part 2: Electrofusion welding
SANS 10268-3	2005	1.01	Welding of thermoplastics - Welding processes Part 3: Hot-gas welding
SANS 10268-4	2004	1.01	Welding of thermoplastics - Welding processes Part 4: Hot-gas extrusion welding
SANS 10268-5	2004	1.01	Welding of thermoplastics - Welding processes Part 5: Solvent welding
SANS 10268-6	2003	1.00	Welding of thermoplastics - Welding processes Part 6: Ultrasonic welding, staking and insertion
SANS 10268-10	2009	1.03	Welding of thermoplastics - Welding processes Part 10: Weld defects





The 5M's affecting the Weld Quality – Machinery

- The ISO 12176-1 and 12176-2 standards sets the pre-requisites of the equipment to qualify for the HDPE Butt fusion and Electrofusion welding activities.
- DVS 2207-4 elaborates extrusion welding process, parameters and requirements on the extrusion welding equipment and devices.











The 5M's affecting the Weld Quality – Material


Choice of Raw materials used for pipe/fitting manufacture has a major impact in the weld quality.

Requirements for raw materials to be used in the HDPE Pipe manufacture is guided in the relevant product standards. Ex. 4427-1, 4437-1 etc.

PE pipes are designed for a long lifetime (in excess of 100 years) in the underground infrastructure. Indeed, installing the pipe in the ground is the most expensive part of operation (typically 85 – 90% of the project costs) so the last thing a gas or water engineer wants to do is replace the pipes within their working lifetime.

This "Peace of Mind" demands consistent materials and products which can only be achieved if the carbon black or pigment and other essential additives are correctly dispersed in the polymer matrix.

The 5M's affecting the Weld Quality – Management





Assessment of Weld Quality – Butt Fusion Welds



Preparation of Pipe/Fitting Test assemblies ISO 11414

Destructive Testing

Tensile Test ISO 13953

Weld Assessment

Non-Destructive Testing

Long Term Hydrostatic Test @ 80°C ISO 1167 Part 1,3,4



Visual Examination for Weld Defects ISO 21307, SANS 10268-10





Assessment of Weld Quality – Electro Fusion Welds



Weld Assessment

Preparation of Pipe/Fitting Test assemblies ISO 11413

Decohesion Test for assemblies >=90mm OD ISO 13954

Crushing decohesion test for polyethylene (PE) electrofusion assemblies

ISO 13955






Extrusion Welding

Extrusion welding is a manual or semi-automatic welding process which is performed with a welding filler (either in wire or granule form) which is melted/plastified in a system (Extruder)


A welding shoe shaped according to the weld geometry is used to press the plastified/molten filler into the groove of the base material using hot air

The output capacity of the welding machines determines the max weld dimensions and influences the welding speed

The joining pressure is generated by the emerging material from the weld gun and the counterforce of the welder.



Extrusion Welding Gun





Extrusion Welding Process

Weld Preparation


The welding surfaces must be:


• Aligned, held and steady in position

dry, clean, oil- and grease-free


free of loose shavings and

free of notches





Assessment of Weld Quality – Extrusion Welds






15-06-202

Pressure/Leak Test for Extrusion Welds











Weld Factor determination for Extrusion Welds

The tensile welding factor $f_z = F_V/F_B$ is determined from the

- mean values of the fracture forces of the welded test specimens (F_V) and the
- Fracture forces of the reference test specimens (F_B).

If the specimens are stretched before fracture, the force at yield stress shall be taken as the reference value.

Table 4 — Minimum requirements for the tensile welding factor fz

1	2	3	4	5	6
William		Tens	sile welding	factor	
Welding process	PE-HD	PP	PVC-C	PVC-HI PVC-U	PVDF
Heated-tool welding	0,9	0,9	0,8	0,9	0,9
Extrusion welding	0,8	0,8	1 -	-	-
Hot-gas welding	0,8	8,0	0,7	8,0	0,8
Electrofusion welding	0,9	0,9	201	-	-
Solvent welding	+	-	0,8	0,9	0,9





Quality Assurance checklist in HDPE Welding

Document control and distribution according to ISO9001

List of Welders and team showing qualifications, responsibilities, training, experience;

Welding procedures/SoP's;

Signed off weld records

Inspection and test Plan (tailored to suit the specification);

Any other items required by the specification





QA samples in HDPE Welding



						BUTT WELD ASSESMENT	EXTRUSION V	WELD ASSESMENT
S/N		NAMES	PF NUMBER	PUNCH NUMBER	VISUAL	BURST TEST	VISUAL	TENSILE TEST
1	MIRAJI	ALLY	PF - 106	106	GOOD	BURST AT MAX PRESSURE OF 65.74BARS (PASSED)		
2	ABDUL	MOHAMED	PF - 177	177	GOOD	BURST AT MAX PRESSURE OF 65.69 BARS (PASSED)		
3	ILDEFONS	MNIMBO	PF - 282	282	GOOD	BURST AT MAX PRESSURE OF 66.24 BARS (PASSED)	GOOD	PASS
4	IDDI	KASSIM	PF - 298	298	GOOD	BURST AT MAX PRESSURE OF 65.89 BARS (PASSED)	GOOD	PASS
5	JULIUS AMOS	MWINAMILA	PF - 308	308			GOOD	PASS
6	MOHAMED ALNURU	SAFARI	PF - 313	313	GOOD	BURST AT MAX PRESSURE OF 40.16 BARS (PASSED)	GOOD	PASS
7	JAMES	KASAWA	PF - 343	343	GOOD	BURST AT MAX PRESSURE OF 65.74 BARS (PASSED)	GOOD	PASS
8	LEMA	ISSA	PF 382 / 10 / 20	541	GOOD	BURST AT MAX PRESSURE OF 66.29 BARS (PASSED)	GOOD	PASS
9	NGOMELA	OMALI	PF - 362 / 02 / 20	362	GOOD	BURST AT MAX PRESSURE OF 31.08 BARS (PASSED)	GOOD	PASS
10	MFANYEJE	SALEHE	PF - 363	543	GOOD	BURST AT MAX PRESSURE OF 65.39BARS (PASSED)	GOOD	PASS







QA samples in HDPE Welding

			-	WELD	ING	RECOR	D A	ND T	CAI	BLI	C		Form	07.03,	02 Rev 2		Sheet No:	
=	DL/	150	0	Report for he	eated plate	e welding of to	ibular co	mponer	its									
		MITED		Weather Condition	9	1 = sunny		Protective :	Veasure		1 = none		In the car	e of multi-	ola darismati	ings follows	the figures as a	Lance.
lient	MKULA	ZI		(WC)		(2)= dry		(PM)		_	2 = screen			rain and		Tons, runow i	ine rigures as a	Dave
roject	REPAIR	OF THE PIPE	E	7-7-		3 = rain or snowfall					3 = tent		(6.5.34	to in dans	vinuj	-		
order No		1 22				4 = wind					4 = beatin	10					-	
daterial	PE	100				5 = dust		Welding to	achine				1					
	1200	1							Make	17 40 1	-	tuf+ 315	1		Location:	MVI	ISAJI	FARM
	Team Lea		DAN		HANA				Type	1 - 5		TW 319						
		der e of welder N	OJILO	FOPS M	MINN	BO = 1/61	tal		Type Machin	e No		M 15 2 AG		014				
ame an	d signature		OJILO	FOPS M			tal		Machin	e No manufac	ture			014				
ame an	d signature	e of welder No	Pipe Size	Heating Element	NPIW UWA Dragging	Join Pressure(P)	Adjuste	d values	Machin	manufac	ture Shifting	M152A6	COS	0) 4 e No.	Starting	Finish		Remarks
lame an	d signature d signature	e of welder No e of welder No Date (Day/Mth)	Pipe Size	Heating Element Temp® C*	Dragging Force p **	Join Pressure(P) Under Cooling	Adjuste Soak (P)	d values Bead Up	Machin Year of	manufac		M 15 2 AG	COS	Exce		Finish Time		Remarks
lame an lame an	d signature d signature Weld No	e of welder No e of welder No Date (Day/Mth) 2022	Pipe Size (mm)	Heating Element Temp® C * min/max	Dragging Force p ** [bar]	Join Pressure(P) Under Cooling Time (bar)	Adjuste Soak (P)	Bead Up	Machin Year of Soak	Dwell Time	Shifting	Cooling Time Under Join Pressure(P) [min]	Cod WC	e No.	Starting Time. (hrs)	Time		Remarks
lame an	d signature d signature	e of welder No e of welder No Date (Day/Mth)	Pipe Size (mm)	Heating Element Temp® C* min/max	Dragging Force p **	Join Pressure(P) Under Cooling Time (bar)	Adjuste Soak (P)	Bead Up [bar]	Machin Year of Soak	Dwell Time	Shifting	Cooling Time Under Join Pressure(P)	Cod	e No.	Starting Time (hrs)	Time		Remarks
lame an	d signature d signature Weld No	Date (Day/Mth) 2022	Pipe Size (mm) 0 00 x 1 3 S	Heating Element Temp® C * min/max 220	Dragging Force p ** [bar]	Join Pressure(P) Under Cooling Time (bar)	Adjusted Soak (P) [bar]	Bead Up [bar]	Machin Year of Soak	Dwell Time	Shifting	Cooling Time Under Join Pressure(P) [min]	Cod WC	e No.	Starting Time (hrs)	Time 12:59		Remarks
lame and	d signature d signature Weld No	Date (Day/Mth) 2022 S-(1	Pipe Size (mm) 0 OD x 1 3 S 3 S 3 S	Heating Element Temp® C * min/max 220 230	Dragging Force p ** [bar]	Join Pressure(P) Under Cooling Time (bar)	Adjuste Soak (P) [bar]	Bead Up [bar]	Machin Year of Soak	Dwell Time	Shifting	Cooling Time Under Join Pressure(P) [min] I.6 I.6	Cod WC	e No.	Starting Time (hrs)	Time 12:59		Remarks
lame and lame and Ser No	Weld No	Date (Day/Mth) 2022	Pipe Size (mm) 0 0D x 1 3 S 3 S 3 S 3 S	Heating Element Temp® C * min/max 220 220 220	Dragging Force p ** [bar]	Join Pressure(P) Under Cooling Time (bar)	Adjusted Soak (P) [bar]	Bead Up [bar] L18 L18 L18 L18 L48	Machin Year of Soak	Dwell Time	Shifting	Cooling Time Under Join Pressure(P) [min] 1.6 1.6	Cod WC	e No.	Starting Time (hrs) 13:20 14:20 14:20	Time 12:59 12:49 15:11		Remarks
Name and	d signature d signature Weld No	Date (Day/Mth) 2022 SS-11 OS-11 OS-11	Pipe Size (mm) 0 00 x1 3 S 2 IS 3 IS 3 IS	Heating Element Temp® C * min/max 220 230	Dragging Force p ** [bar]	Join Pressure(P) Under Cooling Time (bar)	Adjuste Soak (P) [bar]	Bead Up [bar]	Machin Year of Soak	Dwell Time	Shifting	Cooling Time Under Join Pressure(P) [min] I.6 I.6	Cod WC	e No.	Starting Time (hrs) 13.20 14.20 14.20	Time 12:59		Remarks



WEHOLITE WELDING INSPECTION AND TEST PLAN

THIS DOCUMENT MUST BE COMPLETED IN FULL ON BOTH SIDES



Plasco Order No	Joint Number*	Date	Gap 15mm	Gap >15mm	Standard Root + Cap	Plated Fillet	Box Section	Vertical Dimension	Horizontal Dimension	Temperature	Visual Insp. Sign	Comments
	10		-		TOOR			350	350	22°C	OKILLAN	
	02		-		ROOT			350	350	23.C	OKTHER	
-	03		V		ROOT		1	350	350	24.0	DK TILLY	
	04		V		ROOT			350	350	26°C	OK Nolly	
	05		~		ROUT			350	350	.5000	OK / Katel	
- 45	06		~		ROUT			350	350	27°C	DK Mart	
	60		V		ROOT		1	350	350	26€	OK MARI	
	08	1 -0 !	V		ROOT			350	350	52°C	OK THE	
	09		V		ROOT			350	350	28°6	OK THE	
	10	0	V		ROOT	4		350	350	27°C	OK THE	
	11	115	V		ROOT			350	350	27°C	OK Thates	
	12		V		ROUT	1		350.	350	28°C	OK TRACY	
	13		~	-	ROUT		i i	350	350	58,c	OK JAK	
8	14		/		ROUT			350	350	28°C	DIC 1/4	, b



QA samples in HDPE Welding

and the same of th		
PLASCO L		guerra (m)
	ozi Rozd, Chang'ambr,	
P.O. Box 19956,	Dar és salaam, tánzacio,	21 4500
	12-2199 420/821/821	WE STAND FOR QUALITY
Web: www.plus	ules@places.co.te	
n cos sava pra	40.00.71	
		" SGS LTSAT
		Form 07:02:04 Rev 2
FIE	LD SERVICES JOB OF	RDER COMPLETION FORM
CUSTOMER NAME:	NASTID:	CLSTOM & PURCHASE CROER NUMBER: LC NO: OLCHO
SITE/LOCATION:	P. D. HOX 45% KIGALI RWANDA	DRDER DATE: 11-May-2022
JOB EXECUTED:	OUT WILLIAM PARTIES	USION WELDING EXTRUSION WHILEING
	Teste de	South Committee
BRICT JOB DESCRIPT O	N:	
ANTE	6	
Mac gran	of WEHOLITE papes	on 1400 Sm 8 for SABLYA DAM I
RWANDA K	heavy. Piper wolded	in 9 rows each 78 maker.
21.14.0015	114-62 -1-10064	in I was or In the start !
-		
-	1.1.	- da
COMPLETED ON: -	30 10 2022	TEAM LEADER SIGNATURE:
COMPLETED ON		ENVICEABLE SIGNATURE:
CUSTOMER COMMEN	rs:	
JOB COMPLETED SATIS	TACTORILY: YES V	KC T
200 CD WILLIAM WILL	The state of the s	
		7111
	Jean clarke	#
CUSTOMER NAME: -	AAMUKUMAAM	CUSTOMER SIGNATURE:
	HARVILO KOMBE	THE PARTY OF THE P
	MANITOKOMBIA	TENTION DAY DATE 30/10/909
	MBULLO KOMBIT	BATE: 70 MC 200
	18	DATE: 30 MC 20
	MANIOROMBIA	ONZO BATE: ZO MO 1902
	18	DATE: 30 AC 900
	18	ON20
	18	ONZO

	uzi Rond, Canng ne be. Dar es salcom, Tarzania		ACCC
Te: -255-(c):	22-2199 820/821/823		E STAND FOR GRALITY
Emer: pleasess Wab everplos	eles@plasco.ce.tz		(A) (B)
was wearpite	140.10.12		
			Form 37.32.54 Rev 2
FIE	LD SERVICES JOB OR	DER COMPLETION	FORM
:USTOMER NAME:	MASIFIC ESTATES (1) LID	CUSTOM ER PURCHASE ORD	ER NOMBER: HULLY FAIL
SITE/LOCATION:	IRINGA TANZANIA		DRDER DATE: 28-Nov-2023
IGH EXECUTED:	BUTT WELD ING BLEC INC.	IS DIN NAVI JANG EXTRUSIO	A METOING
38 EF JOB DESCRIPTIO	N:		
			1 11
EXTRUS	HON WELDING	OF 350 muir S	N.4
	POTED OF PUL		
	ING TO CUSTOM		
₹cc083	ING TO CUSTOM	er requiren	
₹cc083	7/12/2022	er requiren	
COMPLETED ON:	109 TO (USTOM) 7/12/2022	er requiren	
COMPLETED ON:	7/12/2022 7/12/2022 78:	TEAM LEADER SIGNATURE:	VENTS.
COMPLETED ON:	7/12/2022 7/12/2022 78:	TEAM LEADER SIGNATURE:	
COMPLETED ON:	109 TO (USTOM) 7/12/2022	TEAM LEADER SIGNATURE:	VENTS.
COMPLETED ON:	7/12/2022 7/12/2022 78:	TEAM LEADER SIGNATURE:	VENTS.
COMPLETED ON:	7/12/2022 7/12/2022 78:	TEAM LEADER SIGNATURE:	VENTS.
COMPLETED ON: COMPLETED ON: COSTON FOR CON MEN. COSTON FOR CONF. COSTON FOR CONF.	7/12/2022 The restored that a perfessioned fast a	TEAM LEADER SIGNATURE:	VENTS.
COMPLETED ON: COMPLETED ON: COSTON FOR CON MEN. COSTON FOR CONF. COSTON FOR CONF.	7/12/2022 The restored that a perfessioned fast a	TEAM LEADER SIGNATURE:	onky!
COMPLETED ON: COMPLETED ON: COSTON FOR CON MEN. COSTON FOR CONF. COSTON FOR CONF.	7/12/2022 7/12/2022 78:	TEAM LEADER SIGNATURE: HG	anks!
COMPLETED ON: COMPLETED ON: COSTON FOR CON MEN. COSTON FOR CONF. COSTON FOR CONF.	7/12/2022 The restored that a perfessioned faut a Massifio Estates (ID)	TEAM LEADER SIGNATURE: NG	anks!
COMPLETED ON: COMPLETED ON: COSTON FOR CON MEN. COSTON FOR CONF. COSTON FOR CONF.	7/12/2022 The restored that a perfessioned fast a	TEAM LEADER SIGNATURES NO:	anks!



Presenter

SAPPMA Webinar III 2023



15 June 2023














Why do we determine weld factors?


Welder, process, equipment, components at a specific location may not result in performing welds

- The components and component supplier/product/s may be non-conforming and can not be welded
- Initial weld factor confirms functionality of the preliminary welding procedure
- ongoing weld factor/s (min 1% of welds) confirms reproducibility







Effect of Force and time





We evaluate the weld results





ISBN 978-0-626-31526-9 SANS 10270:2015

SOUTH AFRICAN NATIONAL STANDARD

Welding of thermoplastics — Approval of welding procedures and welds

ISBN 978-0-626-34357-6

SANS 6269:2005

SANS 21307:2011 ISO 21307:2009

SOUTH AFRICAN NATIONAL STANDARD

Plastics pipes and fittings — Butt fusion jointing procedures for polyethylene (PE) pipes and fittings used in the construction of gas and water distribution systems

ISBN 978-0-626-34817-5

SANS 10268-10:2009

SOUTH AFRICAN NATIONAL STANDARD

Welding of thermoplastics — Welding processes

Part 10: Weld defects









Then we Attestate

attestation



noun

- 1. The act of attesting; a declaration, verbal or written, in support of a fact; evidence; testimony.
- 2. The administration of an oath, as to a military recruit. See attest, 4.
- 3. The act of attesting; testimony; witness; a solemn or official declaration, verbal or written, in support of a fact; evidence. The truth appears from the attestation of witnesses, or of the proper officer. The subscription of a name to a writing as a witness, is an attestation.
- 4. A thing that serves to bearwitness, confirm or authenticate.
- 5. A confirmation or authentication.
- The process, performed by accountants or auditors, of providing independent opinion on published financial and other business information of a business, public agency, or other organization.
- 7. An appearance in print or otherwise recorded on a permanent medium.
- 8. the action of bearing witness
- 9. the evidence by which something is attested






We are Jointly Responsible

SAPPIMA

southern african plastic pipe manufacturers association











Questions and Answers



admin@sappma.co.za